

風險評估與管理 – 捷運建設的經驗

Risk Assessment and Management

- Lessons Learnt in Metro Projects

闕河淵 H.Y. Chuay

BSc MSc PhD PE FICE

13 Nov 20



35年捷運建設: 1986 - 2020

- 可行性研究, 規劃, 基本設計, 細部設計, 施工, 整合測試, 通車履勘
- 業主, 設計顧問, 監督顧問, 土建營造廠商, 機電系統廠商
- 傳統設計後施工, Design-Build, Turnkey, BOT

> 150 km Metro Projects

- MRT, MCT, LRT, 傳統客運/貨運鐵路
- 用地取得, 聯合開發
- 獨立驗證與認證

Independent Verification & Validation,
IV&V

- 價值工程 Value Engineering, VE
- 風險管理 Risk Management



綱要 Outlines

1. 投入風險管理領域之由來 What to attract attention?
2. 風險管理作業 Risk management process
3. 風險管理案例 Cases – Planning/Design, Construction
4. 國際風險管理標準 International standards

Major Accidental Events in Taiwan and Overseas

1994(April)	TRTS-CH221: Excessive ground subsidence during segment replacement in the interface of bored tunnel and vent shaft
1994 (Oct)	Heathrow Express Rail Link: Collapse of a NATM tunnel
1994(Nov)	TRTS-CN252: Ground loss induced by piping in deep excavation of an underground station
1995(April)	TRTS-CN261: Ground loss during TBM-launching
1995(July)	TRTS-CN262: Excessive ground loss during TBM-docking
	TANEEB Suei-shan Tunnel : Series of accident during TBM & NATM tunnelling
2002(Aug,Nov)	THSRC-Hu-ko Tunnel : Ground loss during NATM tunnelling
2003(Feb)	TRTS-CD266: Ground loss during TBM-docking
2003(May)	KRTC-LUO04: Excessive ground loss during TBM-docking

2003(July)

Shanghai Metro 4: Tunnel collapse during the excavation of a cross-passage

2003(Aug)

KRTC-O01: Ground loss induced by piping due to defective diaphragm wall during the excavation of an underground station

2003(Aug)

TRTS-CK570C: Flooding due to a gap btwn the river bank and a pump station

2004(April)

Singapore LTA-MRT Circle Line: Collapse of 33m deep excavation of a cut-and-cover tunnel

2005 (Dec)

KRTC-LUO09: Excessive ground subsidence during the excavation of a sump inside a cross-passage


2007(Jan)

Sao Paulo Metro-Linea 4: Collapse of a NATM tunnel

2008(Nov)

Hanzho Metro – Line 1: Collapse of 16 m deep excavation


Contractors All Risks Insurance & Third Party Liability Insurance of Underground Works (Chuay, 2008)



- KL-MRT2 (2016)
 - Deductible: NT\$7-10m
 - Limit of indemnity: NT\$2,200m

- 台北捷運萬大線 (2014)
 - 自負額: NT\$2-5m
 - 賠償上限: 單一事故NT\$100m
(區段標上限NT\$300m)

捷運工程保險和重大施工意外之統計資料






Problems :

- Nightmare for clients or contractors
 - No offer of insurance policy by insurers
 - High premium but very limited coverage
(low frequency but severe consequence)
- Concerns by insurers
 - Frequency of accidents
 - Severe consequence

Joint Code of Practice for Risk Management of Tunnel Works in the UK

- Discussion at ICE, London in July, 2002 about the "JCoP for the procurement, Design and Construction of Tunnels and Underground Structures in the United Kingdom"
- Jointly produced by Association of British Insurers and British Tunnelling Society in 2003
- Pre-requisite for insurance






ITA (Intern'l Tunnelling Association) Working Group 2 (2004):
Guidelines for tunnelling risk management

ITIG (Intern'l Tunnelling Insurance Group) (2006):
A Code of Practice for Risk Management of Tunnel Works
- Supported by ITA and Intern'l Association of Engineering Insurers

風險定義

- 生命, 財務, 時間, 政治
- 施工, 營運
- 規劃, 設計, 施工階段


The Risk Assessment Process




Risk Level Matrix

★ Frequency of occurrence of a hazardous event	Risk Levels			
Frequent	Undesirable	Intolerable	Intolerable	Intolerable
Probable	Tolerable	Undesirable	Intolerable	Intolerable
Occasional	Tolerable	Undesirable	Undesirable	Intolerable
Remote	Negligible	Tolerable	Undesirable	Undesirable
Improbable	Negligible	Negligible	Tolerable	Tolerable
incredible	Negligible	Negligible	Negligible	Negligible
	Insignificant	Marginal	Critical	Catastrophic
Severity Levels of Hazard Consequence				

計畫管理文件架構




Project Organisational Structure




Case History I

- Kaohsiung MRT R&O Lines
LUO09 Recovery Plan


LUO09 Recovery Plan



LUO09 Recovery Plan



LUO09 Recovery Plan



風險疊加

- 細沙或沉泥/地下水位高
- 設計變更: 二個聯絡通道位於地下道二端, 變更為一個位於地下道中央
- 深度增加
- 聯絡通道上方地下道成為土壤改良作業的障礙
- 集水井設於聯絡通道內

Case History 2: Planning/Design Stage

Necessity of cross-passages in bored tunnels



Prescriptive criteria vs Performance-based approach

- NFPA 130: Standard for Fixed Guideway Transit and Passenger Rail Systems (2007)
 - < 6.2.2.3 Means of egress (Cross-passageways): Not farther than 244 m (800 ft) apart
 - < 1.4 Equivalency: New method, material or device equivalent to or superior to the requirements of this standard with respect to fire and life safety
 - < 4.2.2 Goal: Minimum requirements for those instances where "noncombustible materials are not used"





- 
- 定量風險評估

Quantitative Risk Assessment, QRA

Fault Tree Analysis, FTA 災害樹分析

- Data base from UK EMU operation of 34 years
- Data from KCRC EMU operation of 14 years
- Internal fire event: 20 month return period
- External fire event: 15 month return period






Event Tree Analysis, ETA

事件樹分析

Event Trees

Fire in Passenger Carriage In Single Track Tunnel (Internal Fires)

Frequency of Fire in sector which could result in a train stop in tunnel.	Is fire extinguished locally?	Does train proceed out of the tunnel?	Is the stop controlled or uncontrolled?	Does the fire size remain below critical threshold during evac. in tunnel?	Type of evacuation required	Fault sequence number.	Frequency
Fires/year	Y/N	Y/N	C/UC	Y/N	-	-	-



2 Int - Evacuation in Tunnel with uncontained smoke and controlled Stop

Fully Loaded Trains (Frequencies, Consequences, Risks)


From Fault Sequence Number 4	Are evacuation procedures correctly implemented?	Can passengers exit through nearest intervention point?	Does ventilation system in non-incident tunnel operate correctly?	Is the longitudinal ventilation system switched on in incident tunnel and operated correctly?	Frequency (ev./Yr)	Consequence (N. of people affected)
	Y/N	Y/N	Y/N	Y/N		
	Y	Y	Y	Y	0.995 2.59E-05	0.00E+00
	Y	Y	N	Y	0.995 2.60E-05	0.00E+00
	Y	Y	N	N	0.005 1.30E-07	0.00E+00
	Y	N	Y	Y	0.995 1.30E-07	0.00E+00
	Y	N	Y	N	0.005 6.53E-10	2.70E+01
	Y	N	Y	Y	0.995 0.00E+00	1.00E+01
	Y	N	Y	N	0.995 0.00E+00	1.80E+01
	N	Y	Y	Y	0.000 0.00E+00	0.00E+00
	N	Y	Y	N	0.005 0.00E+00	1.50E+01
	N	N	Y	Y	0.005 0.00E+00	2.70E+01
	N	N	Y	N	0.005 0.00E+00	0.00E+00
	N	N	N	Y	0.005 0.00E+00	0.00E+00
	N	N	N	N	0.005 0.00E+00	2.70E+01
	Y	Y	Y	Y	0.995 8.62E-06	1.50E+01
	Y	Y	N	Y	0.995 8.67E-06	9.07E-10
	Y	Y	N	N	0.005 4.33E-08	2.70E+01
	Y	N	Y	Y	0.995 4.33E-08	2.25E+01
	Y	N	Y	N	0.005 2.16E-10	4.56E-12
	Y	N	Y	Y	0.995 0.00E+00	1.50E+01
	Y	N	Y	N	0.995 0.00E+00	2.70E+01
	N	Y	Y	Y	0.000 0.00E+00	0.00E+00
	N	Y	Y	N	0.005 0.00E+00	2.25E+01
	N	N	Y	Y	0.005 0.00E+00	4.05E+01
	N	N	Y	N	0.005 0.00E+00	0.00E+00
	N	N	N	Y	0.005 0.00E+00	0.00E+00
	N	N	N	N	0.005 0.00E+00	4.05E+01
						7.29E-07

Risk /yr			Eq. Injuries	< 10 Eq. Injuries	10 - 100 Eq. Injuries	100 - 1000 Eq. Injuries
Minor Injury	Major Injury	Eq. Injury				
0.00E+00	0.00E+00	0.00E+00	0			
0.00E+00	0.00E+00	0.00E+00	0			
0.00E+00	0.00E+00	0.00E+00	0			
2.22E-10	9.23E-11	6.30E-11	5	6.30E-11		
0.00E+00	0.00E+00	0.00E+00	2	0.00E+00		
0.00E+00	0.00E+00	0.00E+00	3	0.00E+00		
0.00E+00	0.00E+00	0.00E+00	3	0.00E+00		
0.00E+00	0.00E+00	0.00E+00	5	0.00E+00		
1.62E-06	6.77E-07	4.62E-07	3	4.62E-07		
1.47E-08	6.12E-09	4.18E-09	5	4.18E-09		
1.22E-08	5.10E-09	3.48E-09	4	3.48E-09		
1.11E-10	4.62E-11	3.15E-11	7	3.15E-11		
0.00E+00	0.00E+00	0.00E+00	3	0.00E+00		
0.00E+00	0.00E+00	0.00E+00	5	0.00E+00		
0.00E+00	0.00E+00	0.00E+00	4	0.00E+00		
0.00E+00	0.00E+00	0.00E+00	7	0.00E+00		
1.65E-06	6.88E-07	4.69E-07	4.69411E-07	0	0	

3.48E-05
From nodes 4

External fire In Single Track Tunnel


Frequency of Fire in sector which could result in a train stop in tunnel.	Does train proceed out of the tunnel?	Is the stop controlled or uncontrolled?	Is fire extinguished locally?	Does the fire separation maintain its integrity during evac.?	Type of evacuation required	Fault sequence number.	Frequency
Fires/year	Y/N	C/UC	Y/N	Y/N			




1 Ext - Evacuation for External Fires, Controlled stop, limited smoke & heat exposure.

From Fault Sequence Number 2	Are evacuation procedures correctly implemented?	Is the nearest IP available?	Does ventilation system in non-incident tunnel operate correctly?	Is the longitudinal ventilation system switched on in incident tunnel and operating correctly?	Frequency (per yr)	Consequence (N. of people affected)	Risk Yr				4-10 Eq. Injuries	10-100 Eq. Injuries	100-1000 Eq. Injuries
							Minor Injury	Major Injury	Eq. Injury	Eq. Injuries			
1.73E-04	1.34E-04	0.000	0.000	0.000	2.78E-06	1.00E+01	1.67E-05	6.64E-06	4.73E-06	2	4.73E-06		
		Y	0.935	1.32E-04									
		N	0.005	6.66E-07		1.40E-08	1.80E+01	1.51E-07	6.20E-08	4.20E-08	3	4.20E-08	
		Y	0.995	6.26E-07									
		N	0.005	6.70E-07		1.40E-08	1.50E+01	1.56E-07	5.23E-08	3.57E-08	3	3.57E-08	
		Y	0.995	6.26E-07									
		N	0.005	6.70E-07		7.01E-11	2.70E+01	1.14E-09	4.73E-10	3.23E-10	3	3.23E-10	
		Y	0.995	6.26E-07									
		N	0.005	6.70E-07		0.00E+00	1.00E+01	0.00E+00	0.00E+00	2	0.00E+00		
		Y	0.995	6.26E-07									
		N	0.005	6.70E-07		0.00E+00	1.00E+01	0.00E+00	0.00E+00	3	0.00E+00		
		Y	0.995	6.26E-07									
		N	0.005	6.70E-07		0.00E+00	1.50E+01	0.00E+00	0.00E+00	3	0.00E+00		
		Y	0.995	6.26E-07									
		N	0.005	6.70E-07		0.00E+00	2.70E+01	0.00E+00	0.00E+00	5	0.00E+00		
1.73E-04	1.34E-04	0.000	0.000	0.000	0.00E+00	1.00E+01	0.00E+00	0.00E+00	0.00E+00	2	0.00E+00		
		Y	0.995	4.42E-05									
		N	0.005	2.33E-07		0.29E-07	1.50E+01	8.33E-06	3.47E-06	2.37E-06	3	2.37E-06	
		Y	0.995	4.42E-05									
		N	0.005	2.33E-07		1.65E-09	2.70E+01	7.53E-08	3.14E-08	2.14E-08	3	2.14E-08	
		Y	0.995	4.42E-05									
		N	0.005	2.33E-07		4.66E-09	2.25E+01	0.29E-08	2.02E-08	1.78E-08	4	1.78E-08	
		Y	0.995	4.42E-05									
		N	0.005	2.33E-07		2.34E-11	4.00E+01	5.68E-10	2.37E-10	1.61E-10	7	1.61E-10	
		Y	0.995	4.42E-05									
		N	0.005	2.33E-07		0.00E+00	1.50E+01	0.00E+00	0.00E+00	3	0.00E+00		
		Y	0.995	4.42E-05									
		N	0.005	2.33E-07		0.00E+00	2.70E+01	0.00E+00	0.00E+00	5	0.00E+00		
		Y	0.995	4.42E-05									
		N	0.005	2.33E-07		0.00E+00	2.25E+01	0.00E+00	0.00E+00	4	0.00E+00		
		Y	0.995	4.42E-05									
		N	0.005	2.33E-07		0.00E+00	4.05E+01	0.00E+00	0.00E+00	7	0.00E+00		
0.350	4.47E-05	0.000	0.000	0.000	2.09E-02			2.64E-05	1.06E-05	2.22E-06	7.22E-06	0.00E+00	0.00E+00

Structure of Tunnel Fire Risk Model




Standard Fire Curve for DFRA and QRA Tunnel Fire Analysis




1.5 mins ,
2MW

56 mins ,
10MW

Structure of KCRC TFRM



Trend Graph for Individual Equivalent Injury Risk



Necessity of cross-passages in bored tunnels (Kowloon Canton Railway 2003)

- Deterministic Fire Risk Assessment of Tunnel fires
 - < Principle: Passengers to walk away in tunnel fire and reach a place of safe passage
 - < Evacuation strategy of passengers in tunnel fire
 - Transverse vs Linear evacuation routes
 - Duration of evacuation against various cross-passage spacing
 - Evacuation through side doors or end doors
 - < Key factors in the safety of evacuation
 - Evacuation in the correct direction
 - Correct operation of the ventilation system

Possible Solution: *Transverse* vs. *Linear* evacuation



Necessity of cross-passages in bored tunnels (Kowloon Canton Railway 2003) Results of analyses

- No measurable safety benefit provided by a closely spaced cross-passage configuration
- Vital safety factors: Initiation of evacuation in the correct direction &
Correct operation of the ventilation system
- Simple procedure for linear evacuation providing better crowd control and reducing the likelihood of accidents




Case History 3


- Kuala Lumpur MRT Line 2
Chan Sow Lin Station, CSLS

**FEATURES
ALREADY
EXPOSED in
Chan Sow Lin
excavation.**

**Multiple caves
and cavities were
unearthed during
excavation.
Extreme Karst
condition exhibit
very variable
combination of
black organic
material infills to
highly weathered
rock.**



Geological Conditions




Ground Investigation:


1. Soil Investigation
2. Drilled Holes for Curtain Grouting Surrounding Station Perimeter (2m to 4m spacing c/c)
3. Bored Pile Drilled Hole
4. Microgravity Survey
5. Borehole Televiewer
6. Rock Mapping on Rock Face

Geological Conditions

Deep valley cutting across Chan Sow Lin Station footprint shown by microgravity survey (in blue) and SI data/piling record/grouting record




3D VOXLER MODEL



Microgravity Survey & Voxler Rockhead Model


Site Plan



Station Information

Length	200 m
Width	21.6 m
Depth	40 m
Entrance	3 nos
Linkway to LRT	1 nos
No. of Floors	5

Station Configuration




Example of What Could Go Wrong

Example of localized ground loss (rock slip) due to unforeseen rock joint formation behind exposed rock face.

Despite extensive soil investigation and geophysics work were



Typical Cross-Section



Risk Rating Matrix

		Risk Area	IMPACT SEVERITY					
			1	2	3	4	5	
			Minimal	Minor	Moderate	Major	Severe	Catastrophic
IMPACT CAPACITY	Financial	<1 mill	>1 mill ≤ 5 mill	> 5 mill ≤ 10 mill	> 10 mill ≤ 20 mill	> 20 mill	> 1 bill	
	Safety	None	First aid required	Medical treatment required	Serious injuries	A fatality case		
	Programme	< 4 wks	> 4 wks ≤ 8 wks	> 8 wks ≤ 12 wks	> 12 wks ≤ 16 wks	> 16 wks		
	Third Party Impact	Negligible damage	Minor damage some repairs required	Moderate to high damage requires specialist to repair	Significant / permanent damage	Widespread, substantial/ permanent damage		
	Environmental Impact	Minor contamination of spoils at works area	Slight contamination of spoils at works area - some precaution's necessary result in slight delay	Contamination/pollution into public space causing public nuisance/discomfort	Major source of contamination causing adverse public health & well being	Catastrophic environmental damage		
LIKELIHOOD	5	Almost Certain - happens frequently (more than 10 times within the project)	5	10	15	20	25	
	4	Very Likely - could happen frequently (more than 3 times within the project)	4	8	12	16	20	
	3	Likely - could happen occasionally (less than 3 times within the project)	3	6	9	12	15	
	2	Unlikely - could happen rarely (1 time within the project)	2	4	6	8	10	
	1	Very Unlikely - probably will not happen (has never occurred)	1	2	3	4	5	

 Low
 Medium

 High
 Very High



Risk Assessment

Top 2 risks anticipated due to DUKE3 piling work are:

- 1) Safety related to rock slip
- 2) Impact to programme/cost

Risk Assessment – Safety Related to Rock Slip

- **Likelihood: Category 2/3 [Risk Rating Matrix]**

- Site investigations were carried out according to best practice.
- Geological mapping was carried out during excavation and the design of rock bolts and shotcrete was done accordingly.
- However, geological conditions can not all be fully exposed.

- **Impact Severity: Category 5 [Risk Rating Matrix]**

- 50-150 workers in any time; therefore, the consequence can be catastrophic if a rock slip occurs.

- **Level of Risk: Severe (Cat 5) x Unlikely/Likely (Cat 2/3) = High (10-15)**


Mitigation Measures

By DUKE 3

- No piling work until the completion of concourse slab
- One pile at a time after the completion of concourse slab.


By MGKT

- Remove the workers 20m to either side of piling point. No activity in the 40m cordoned-off zone during active piling.



For example:
when P42-L piling work is on-going,
MGKT's no-work zone shall be as
highlighted.


Mitigation Measure



Proposed 2 Level Structural Completion of Station Box

Structural Completion until Concourse Level Slab Level


- 1) After the completion of concourse slab, the remaining rock face height is still approx. 20m.



CSLS Box Cross Section




Mitigation Measure



Case History 4: Design Stage

Design of R10 Cofferdam (Kaohsiung MRT Project)

- Risk assessment: Hazard identification and mitigation measures
 - < 140 m in diameter and 20/27 m deep with no strutting system in urban area
 - < Hoop pressure = Ground water pressure (80%) + Earth pressure (20%)
 - < Verticality of diaphragm wall
 - < Glass-fiber re-bar for TBM-launching
 - < External excavation after the concreting of the circular structure
 - < Geotechnical monitoring system



93.02.23
圓形部



Risk assessment: Hazard identification and mitigation measures

- < 140 m in diameter and 20/27 m deep with no strutting system in urban area
- < Hoop pressure = Ground water pressure (80%) + Earth pressure (20%)
- < Verticality of diaphragm wall
- < Glass-fiber re-bar for TBM-launching
- < External excavation after the concreting of the circular structure
- < Geotechnical monitoring system

R10 Risk Register

Period	Phenomenum		Influence	Pre RCM				Cause	Measures		Post RCM						
	Large scale	Small scale		Likelihood	Construct ion Safety		Environ ment		Contents	In charge	Lidelihood	Construct ion Safety		Enuiron ment			
					S	R	S					R	S	R	S	R	
Inner soil excavation period	Abnormal behavior of diaphragm wall and ring beam	Propriety of design condition	Diaphragm safety is worried because of eccentric pressure	4	3	H	2	M	<ul style="list-style-type: none"> Ground unevenness Lack of geological survey Underestimate in design 	Design	<ul style="list-style-type: none"> Make detail geologic survey Considering unevenness of soil layer, eccentric soil pressure is assumed to be 20% of standard soil pressure 	Design dept./Sinotech	1	1	L	1	L
		Ground water level		5	2	H	1	M									
							Monitor	<ul style="list-style-type: none"> Adopt automatic monitor system Pore water pressure gauge 	Design dept. Construction dept	1	1	L	0	L			



International Standards

- ISO3100:2009 Risk Management – Principles and Guidelines, supported by “Practice standard for project risk management” 2009 published by Project Management Institute

Risk Management – Key Elements

- Risk Manager 風險經理
- Risk Register 風險登記冊
- Risk Owner/Action Owner 風險管理人 / 風險行動人
- Top ten risks

Thanks for your attention

